

# Filing Discrepancies and Repair

FCC Discrepancies can cost tens of thousands of dollars when your sites are out of compliance, why not monitor your exposure before they do? We have incorporated our experience with field, engineering, regulatory, GIS, FCC and FAA filings into a product that shows both mapping and graphing of the tolerances. Since regulatory is ongoing, this process is always being updated and can be connected with your site details. Our FAA and FCC filing services are also just a click away for fast clean-up work. Each tolerance is weighted differently with the greatest push toward red, which shows those with the heaviest exposure to fines.

The screenshot displays the SiteSync software interface. The main window shows a map of Lawrence, KS, with various discrepancy markers and a detailed data table for site ID 841. The table includes columns for Demo Co, FCC, FAA, GE (AMSL), Structure Ht., Overall Ht. (AGL), and Overall Ht. (ASL). The data for site 841 is as follows:

Demo Co	FCC	FAA	GE (AMSL)	Structure Ht.	Overall Ht. (AGL)	Overall Ht. (ASL)
38° 50' 0.0"	38° 50' 15.0"	38° 50' 15.0"	320.00m/1,049.87Ft	274.00m/900.00Ft	6.17Ft	594.10m/1,949.00Ft
320.00m/1,049.87Ft	320.00m/1,049.87Ft	320.10m/1,050.20Ft	274.00m/898.95Ft	274.00m/898.95Ft	274.00m/898.95Ft	594.10m/1,949.00Ft

Below the table, there are sections for 'Exact FCC Match', 'Nearby FCC Matches', 'Exact FAA Match', and 'Nearby FAA Matches'. The 'Exact FCC Match' section shows a distance from the site of 0.00m and 0.95ft. The 'Exact FAA Match' section shows a distance from the site of 0.00m and 0.95ft. The 'Nearby FCC Matches' section shows a distance from the site of 0.00m and 0.95ft. The 'Nearby FAA Matches' section shows a distance from the site of 0.00m and 0.95ft.

Our auto matching to existing and/or nearest structures to your sites allows for discrepancy repairs and shows your internal data matches to FCC and FAA filed information.

Our Discrepancy Filing access is part of the  
**The SiteSync Platform™**



**\$2,057.00 / yr**

Available with request in the SiteSync Regulatory Package.

Dirt Simple Telecom Tools



425-643-5000

www.wirelessapplications.com

